US EPA RECORDS CENTER REGION 5

March 12, 1979

To:

Files

From:

R. Cleaton

Subject: Inspection at U. S. Steel, Garv

This inspection is presented in memo form due to lack of space on the regular form for the details involved in inspection of this facility.

The regular outfall inspection was as follows:

Head of River

8 . 26 1 1 1 11

GW-1

Clear-low flow

Heavy popping oil in discharge. Later Mr. Vic Nordlund and the wirter drove to Gary Tube works where we found their treatment facilities to need cleaning on the ground and the facilities themselves to need cleaning and maintenance. Mr. Nordlund contacted Gary Tube Works personnell about

these conditions.

GW-la

GW-2

GW2a &3a

Down-no flow temporary boom OK and doing job. skimmer operating OK

clear-iron algae in water

GW 4

Virginia St Bridge

GW-5

GW-6

Clear medium oil sheen on river

slight turbidity

clear

Inspection was made of the Blast Furnace system at this point in travel It was noted that one of the clarification units was down for construction purposes. The dredge was not operating and a heavy accumulation was noted on the bed of the settling lagoon

GW-7

GW-7a

GW-8 &9

clear

slightly red color water from the BOP shop

Broadway Bridge

Slight oil observed on the river even with

the boom at GW-9 operating.

No inspection was made of GW-10a and lla due to inaccesible from snow preventing driving to outfalls.

GW-14

slight yellow color. It was reported by Mr. NOrdlund that changes have been made in upstream sewer sonccections that will eventually clear up this outfall. Changes

made in Dedember 1978.

E cell down. West Cell good.sKimmers not operating. Water conditions fair to good.

GW-17

Inspections at Lake front outralls were limited to STL-6 due to road and icing conditions.

STL-6

heavy oil and turbidity was found to be discharging from this outfall. Insepction of treatment facilities showed that oil was coming from the 84 inch mill roughing pit. Also some of the filters did not appear to be working to capacity.